

PAINTING AND PREPARATION OF STEEL DOORS

SURFACE PREPARATION

- 1) Remove residual contamination with a hand brush and water, solution of 1/2 cup laundry detergent per five gallons of warm water. Scrub to remove soil, oil, grease and chalking. Rinse clean with water.
- 2) To use power spray, use solution of 1/2 cup laundry detergent to five gallons of warm water. Scrub to remove sol, oil grease and chalking. Rinse clean with water.

PAINTING RECOMMENDATION

- 1) Paint all surfaces with two (2) coats of a high quality latex base exterior paint.
- 2) Assure excess paint behind door jambs or between sections is removed or fully cured to prevent popping or damage.