



PAINTING AND PREPARATION OF STEEL DOORS

SURFACE PREPARATION

1) Remove residual contamination with a hand brush and water, solution of 1/2 cup laundry detergent per five gallons of warm water. Scrub to remove soil, oil, grease and chalking. Rinse clean with water.

2) To use power spray, use solution of 1/2 cup laundry detergent to five gallons of warm water. Scrub to remove soil, oil grease and chalking. Rinse clean with water.

PAINTING RECOMMENDATION

1) Paint all surfaces with two (2) coats of a high quality latex base exterior paint.